

Release Notes for DrayTek Vigor 2765 series (UK/Ireland)

| | |
|-------------------|---|
| Firmware Version | 4.5.2.2 (Formal Release) |
| Release Type | Important – Review release notes and upgrade if the changes affect your system stability, performance, or security |
| Build Date | 20 th March 2026 |
| Release Date | 2 nd April 2026 |
| Revision | 6460_3e8388282b |
| Applicable Models | Vigor 2765, Vigor 2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

IMPORTANT NOTE: This firmware release is classified as important because it includes improvements to WUI-related security.

New Features

(None)

Improvements

1. Enhanced Web GUI Security
 2. All VPN services are now disabled by default
 3. Improvements to the Remote Management TOTP feature
 4. Further improvements to the periodic information sending mechanism related to VigorACS
-

Firmware File Types

The ZIP file contains the firmware with two different file extensions, .ALL and .RST. The firmware is identical, but the RST file contains factory default settings. If you install the ALL file, your router will retain all existing settings. If you use the RST file, all settings will be wiped from your router.

Modem Codes

There are five firmware variants available for download.

| Download Filename | Firmware Filename | Modem Code | |
|---------------------|-------------------------|------------|--------|
| | | VDSL | ADSL |
| v2765_4522_BT.zip | v2765_4522BT_8D1B17.all | 8D1B17 | 8D0E11 |
| v2765_4522_MDM0.zip | v2765_4522_8B0F07.all | 8B0F07 | 8B0701 |
| v2765_4522_MDM1.zip | v2765_4522_8B1117.all | 8B1117 | 8B0701 |
| v2765_4522_MDM2.zip | v2765_4522_8D1917.all | 8D1917 | 8D0C11 |
| v2765_4522_MDM3.zip | v2765_4522_77C717.all | 77C717 | 8D0C11 |
| v2765_4522_MDM4.zip | v2765_4522_8D1C17.all | 8D1C17 | 8D0E11 |

We recommend using firmware "v2765_4522BT_8D1B17.all" unless you have specific line issues.

Upgrade Instructions

It is recommended that you take a configuration backup prior to upgrading the firmware. This can be done from the router's system maintenance menu.

To upgrade firmware, select '*firmware upgrade*' from the router's system maintenance menu and select the correct file. Ensure that you select the ALL file unless you want to wipe out your router's settings back to factory default.



Manual Upgrade

If you cannot access the router's menu, you can put the router into 'TFTP' mode by holding the RESET whilst turning the unit on and then use the Firmware Utility. That will enable TFTP mode. TFTP mode is indicated by all LEDs flashing. This mode will also be automatically enabled by the router if there is a firmware/settings abnormality. Upgrading from the web interface is easier and recommended – this manual mode is only needed if the web interface is inaccessible.

| | |
|-------------------|---|
| Firmware Version | 4.5.2.1 (Formal Release) |
| Release Type | Important – Review release notes and upgrade if the changes affect your system stability, performance, or security |
| Build Date | 16 th January 2026 |
| Release Date | 4 th February 2026 |
| Revision | 6453_b38a15d3f2 |
| Applicable Models | Vigor 2765, Vigor 2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

IMPORTANT NOTE: This firmware release type is important because it corrected an issue related to unexpected reboots under some circumstances if the WAN connection method is set to DHCP mode.

New Features

(None)

Improvements

1. The DHCP related WAN stability improvements
2. Fix an issue where router did not send periodic information intermittently

| | |
|------------------|------------------------|
| Firmware Version | 4.5.2 (Formal Release) |
|------------------|------------------------|

| | |
|-------------------|---|
| Release Type | Critical – Upgrade recommended immediately |
| Applicable Models | Vigor 2765ac, Vigor 2765Vac |

| | |
|-------------------|--|
| Release Type | Regular – Upgrade recommended when convenient |
| Applicable Models | Vigor 2765 |

| | |
|-----------------|--------------------------------|
| Build Date | 12 th November 2025 |
| Release Date | 4 th December 2025 |
| Revision | 6451_0a62888c85 |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

IMPORTANT NOTE: This firmware is marked as critical for Vigor 2765ac and Vigor 2765Vac due to security improvements in the WLAN drivers. If upgrading is not immediately possible, consider disabling WLAN functionality or isolating the devices from the rest of the network as a temporary precaution.

New Features

(None)

Improvements

1. WLAN driver updates with security improvements (CVE-2025-20710, CVE-2025-20715~20716, CVE-2025-20718~20720, CVE-2025-20724, CVE-2025-20733~20734, CVE-2025-20736~20739).
 2. AutoHunt mechanism improvements, including detection of WAN2 online/offline status
 3. Fix for issues related to 'device loss of connection'
 4. Improvements to the periodic inform mechanism used with VigorACS
 5. Incorrect characters were shown on the note of the [VPN and Remote Access] > [PPP General Setup] page
 6. Wrong settings could have been saved for Proposal Encryption & DH Group for LAN to LAN IPsec VPN after saving the profile
 7. Fix for the issue with failure to set and save Group 20 for IKE Phase 1 Settings, Proposal DH Group in [VPN and Remote Access] > [LAN to LAN] > [Dial-Out Settings]
-

| | |
|-------------------|---|
| Firmware Version | 4.5.1 (Formal Release) |
| Release Type | Critical – Upgrade recommended immediately |
| Build Date | 25 th August 2025 |
| Release Date | 11 th September 2025 |
| Revision | 6276_a37f15c088 |
| Applicable Models | Vigor 2765, Vigor 2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

New Features

(None)

Improvements

1. Improved Web GUI Security
2. Added SNMP OID support for WAN uptime
3. Compliance with EN 18031 cybersecurity requirements
4. Wi-Fi driver security improvements (CVE-2025-20681~20684, CVE-2025-20688~20692)
5. Add option to enable/disable force admin password change .def file
6. The router could stop responding when it was provisioned by ACS with an XML file that included specific VPN settings
7. Fixed an issue where an unnecessary object menu appeared in Object Settings
8. Fixed an issue where PPTP, IPsec, and L2TP VPN services were enabled by default
9. Fixed system stability issues related to WCF, VoIP/KMC56 buffer leaks, TR-069, and excessively long URLs

| | |
|------------------|--------------------------|
| Firmware Version | 4.4.5.8 (Formal Release) |
|------------------|--------------------------|

| | |
|-------------------|---|
| Release Type | Critical – Upgrade recommended immediately |
| Applicable Models | Vigor 2765ac, Vigor 2765Vac |

| | |
|-------------------|--|
| Release Type | Regular – Upgrade recommended when convenient |
| Applicable Models | Vigor 2765 |

| | |
|-----------------|-----------------------------|
| Build Date | 20 th March 2025 |
| Release Date | 24 th March 2025 |
| Revision | 5806_9942fd7deb |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

New Features

(None)

Improvements

1. Support for the transmission of multiple fragmented packets
2. WLAN driver updates with security improvements (CVE-2025-20631, CVE-2025-20632 and CVE-2025-20633). Note that this release type is marked as Critical for the Vigor 2766ac and 2766Vac variants only

| | |
|-------------------|--|
| Firmware Version | 4.4.5.6 (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 20 th December 2024 |
| Release Date | 10 th January 2025 |
| Revision | 5799_afc25c59f7 |
| Applicable Models | Vigor 2765, Vigor 2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

New Features

(None)

Improvements

1. RSSI for WiFi clients is included in the SysLog
2. The router could stop responding due to increased memory usage caused by the New Country Object database
3. Protection added to prevent memory leak
4. Improvements to the random wireless disconnection issue
5. VPN traffic could not pass through Multiple SA (BGP related)
6. Some TR-069 parameters could not be updated via VigorACS
7. Removed older ciphers from SSH server supported ciphers list
8. The router would not allow to create LetsEncrypt certificate with NO-IP domain name
9. Improvements to the TR-069 parameter tree being read by ACS server
10. The router could become unresponsive when changing the 2.4GHz channel from 11 to Auto
11. In some circumstances both 2.4G and 5G Wifi could stop working
12. Fix an issue with access to the router's Web Interface from the Internet via HTTP or HTTPS
13. In some circumstances the router could become unresponsive when the USB disk was used

| | |
|-------------------|---|
| Firmware Version | 4.4.5.5 (Formal Release) |
| Release Type | Critical – Upgrade recommended immediately |
| Build Date | 25 th October 2024 |
| Release Date | 20 th November 2024 |
| Revision | 5784_97ddf1544e |
| Applicable Models | Vigor2765, Vigor2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

New Features

(None)

Improvements

1. Web GUI security improvements
2. The router could stop responding after making some phone calls

Known Issues

1. Central AP Management profiles can't be applied to specific access points

| | |
|-------------------|---|
| Firmware Version | 4.4.5.3 (Formal Release) |
| Release Type | Critical – Upgrade recommended immediately |
| Build Date | 29 th July 2024 |
| Release Date | 13 th August 2024 |
| Revision | 5611_5d17be0def |
| Applicable Models | Vigor2765, Vigor2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

New Features

(None)

Improvements

1. Web GUI security improvements

Known Issues

Central AP Management profiles can't be applied to specific access points

| | |
|-------------------|--|
| Firmware Version | 4.4.5.1 (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 27 th June 2024 |
| Release Date | 9 th August 2024 |
| Revision | 5524_ea9ddf03f7 |
| Applicable Models | Vigor2765, Vigor2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

New Features

(None)

Improvements

1. Password mechanism changed to force admin to change the password from the default password

Known Issues

1. Central AP Management profiles can't be applied to specific access points

| | |
|-------------------|--|
| Firmware Version | 4.4.3.2_BT (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 5th March 2024 |
| Release Date | 20 th June 2024 |
| Revision | 4881_1f760399bf |
| Applicable Models | Vigor2765, Vigor2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

New Features

(None)

Improvements

1. Improvements to the Web GUI Security (CVE-2024-23721)
2. Login to the GUI could fail when WAN was up

Known Issues

1. Central AP Management profiles can't be applied to specific access points

| | |
|-------------------|--|
| Firmware Version | 4.4.3_BT (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 2 nd October 2023 |
| Release Date | 17 th November 2023 |
| Revision | 4859_7393299158 |
| Applicable Models | Vigor2765, Vigor2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

New Features

1. Support for the new WCF provider – URL Reputation. If you have an existing activate licence, then this will be upgraded to the URL Reputation licence
2. Support for WireGuard VPN
3. TOTP 2-factor authentication (Google Authenticator) is now available for authenticating Remote Dial-In User VPN connections
4. Added support for DWM-222 USB dongle
5. Support for VoIP(SIP)/TR-069 over IPv6
6. Added support for QoS packet priority
7. Upload of the certificate chain PKC 12 files is now supported
8. Customised logo can be displayed on the login greeting page

Improvements

1. All VPN services are now disabled by default
2. The 'VPN' interface can be selected on the [NAT] > [Open Port] pages
3. New TR-069 parameters added for Alias-Based and Instance Wildcards
4. Support for HTTP compression to reduce the TR-069 payload size
5. The admin password on AP Management WLAN profile can exceed 16 characters
6. The default SSID name syntax is now based on any characters and the 6-digits suffix of the LAN MAC address, e.g., *DrayTek-xxxxxx*
7. Improvements to the Web GUI Security
8. Support for additional SMS commands
9. Support for writable/read-only TR-069 parameters notes
10. Improvements to the mechanism handling DNS PTR records
11. In some circumstances the DHCP relay did not work
12. The router did become inactive after WAN IPv6 was renew
13. Fixed the Bridge VLAN over mesh network connectivity
14. Fixed an issue that could result in 'Firmware Damage' being reported when upgrading from VigorACS
15. Improvements to the issue with empty .json response for CPE when using VigorACS API
16. In some circumstances graphs displayed on the VigorACS page would show gaps
17. The WPS button would not enable nor disable the wireless bands
18. The VoIP QoS graph would begin recording with a delay

19. The router could stop responding when L2TP with IPsec (LAN to LAN) VPN profile was created
20. The Let's Encrypt certificate could not be renewed automatically
21. Fixed an issue with the key data loss for OpenVPN client config file when exported from VigorACS
22. When OpenVPN to Pfsense was established, the push route from the server could not be completed
23. Fixed an issue with error message of HTTP Content Error that would appear while trying to import ovpn (OpenVPN) file
24. The router could stop responding when IKEv2 re-dialled and the local ID was set to 32 characters
25. The Firmware Damage state would remain after uploading the wrong file (file size 0)
26. The Smart VPN Client 2FA window did not appear when using IKEv2 EAP and any router LAN IP address except the first one

Known Issues

1. Central AP Management profiles can't be applied to specific access points

| | |
|-------------------|--|
| Firmware Version | 4.4.3_BT (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 2 nd October 2023 |
| Release Date | 17 th November 2023 |
| Revision | 4859_7393299158 |
| Applicable Models | Vigor2765, Vigor2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

New Features

1. Support for the new WCF provider – URL Reputation. If you have an existing activate licence, then this will be upgraded to the URL Reputation licence
2. Support for WireGuard VPN
3. TOTP 2-factor authentication (Google Authenticator) is now available for authenticating Remote Dial-In User VPN connections
4. Added support for DWM-222 USB dongle
5. Support for VoIP(SIP)/TR-069 over IPv6
6. Added support for QoS packet priority
7. Upload of the certificate chain PKC 12 files is now supported
8. Customised logo can be displayed on the login greeting page

Improvements

1. All VPN services are now disabled by default
2. The 'VPN' interface can be selected on the [NAT] > [Open Port] pages
3. New TR-069 parameters added for Alias-Based and Instance Wildcards
4. Support for HTTP compression to reduce the TR-069 payload size
5. The admin password on AP Management WLAN profile can exceed 16 characters
6. The default SSID name syntax is now based on any characters and the 6-digits suffix of the LAN MAC address, e.g., *DrayTek-xxxxxx*
7. Improvements to the Web GUI Security
8. Support for additional SMS commands
9. Support for writable/read-only TR-069 parameters notes
10. Improvements to the mechanism handling DNS PTR records
11. In some circumstances the DHCP relay did not work
12. The router did become inactive after WAN IPv6 was renew
13. Fixed the Bridge VLAN over mesh network connectivity
14. Fixed an issue that could result in 'Firmware Damage' being reported when upgrading from VigorACS
15. Improvements to the issue with empty .json response for CPE when using VigorACS API
16. In some circumstances graphs displayed on the VigorACS page would show gaps
17. The WPS button would not enable nor disable the wireless bands
18. The VoIP QoS graph would begin recording with a delay

19. The router could stop responding when L2TP with IPsec (LAN to LAN) VPN profile was created
20. The Let's Encrypt certificate could not be renewed automatically
21. Fixed an issue with the key data loss for OpenVPN client config file when exported from VigorACS
22. When OpenVPN to Pfsense was established, the push route from the server could not be completed
23. Fixed an issue with error message of HTTP Content Error that would appear while trying to import ovpn (OpenVPN) file
24. The router could stop responding when IKEv2 re-dialled and the local ID was set to 32 characters
25. The Firmware Damage state would remain after uploading the wrong file (file size 0)
26. The Smart VPN Client 2FA window did not appear when using IKEv2 EAP and any router LAN IP address except the first one

Known Issues

1. Central AP Management profiles can't be applied to specific access points

| | |
|-------------------|---|
| Firmware Version | 4.4.2.1_BT (Formal Release) |
| Release Type | Critical – Upgrade recommended immediately |
| Build Date | 11 th January 2023 |
| Release Date | 3 rd March 2023 |
| Revision | 3596_a57ba5a9ff |
| Applicable Models | Vigor2765, Vigor2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

New Features

(None)

Improvements

1. Improvements to the Web GUI Security (CVE-2023-23313)

Known Issues

(None)

| | |
|-------------------|--|
| Firmware Version | 4.4.2_BT (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 17 th May 2022 |
| Release Date | 09 th June 2022 |
| Revision | 3596_a57ba5a9ff |
| Applicable Models | Vigor2765, Vigor2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

New Features

(None)

Improvements

1. Improved Web GUI Security
2. Updated HTTPS mechanism to address the CVE-2022-0778 (OpenSSL)
3. Management Access List now supports IP Objects and IP Groups
4. MAC addresses of clients using IGMP queries are displayed in
[Diagnostics] > [Syslog Explorer]

Known Issues

(None)

| | |
|-------------------|--|
| Firmware Version | 4.4.1_BT (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 14 th February 2022 |
| Release Date | 25 th March 2022 |
| Revision | 2972_7698bd3923 |
| Applicable Models | Vigor2765, Vigor2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

New Features

1. Remote management profile supports the Time-based One-time Password (TOTP) authentication method

Improvements

1. Static route sessions can be processed by hardware acceleration
2. Mesh Root TCP port 9608 could be detected on WAN when enabled
3. Dynamic DNS (DrayDDNS profiles) can be set in round robin or WANx First configuration
4. Routers did not connect to GenieACS servers

Known Issues

(None)

| | |
|-------------------|--|
| Firmware Version | 4.4.0_BT (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 25 th November 2021 |
| Release Date | 30 th December 2021 |
| Revision | 2890_79d39042b |
| Applicable Models | Vigor2765, Vigor2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

New Features

1. Support for IKEv2 fragmentation to improve IKEv2 EAP compatibility
2. Router's DNS server feature can record one domain with multiple IP addresses
3. App-level Bandwidth Limits (e.g. Teams, OneDrive, Steam) can now be configured from [Bandwidth Management] > [Bandwidth Limit] > [APP]
4. Inbound QoS now supports Hardware Accelerated operation
5. [Certificate Management] system now operates in a new way:
 - a. HTTPS certificate for management & SSL VPN is now selected from: [Certificate Management] > [Local Services List]
Reboot the router after changing this setting to use the new certificate
 - b. [Local Certificates] now supports more than 3 certificates
 - c. [Trusted CA Certificates] now supports more than 3 certificates
 - d. Storage for Certificate on each of those pages shows % remaining available space
 - e. Password on Private Key is no longer required when importing Cert + Private Key
6. Wake on LAN via WAN can now be enabled/disabled for allowed IPs or any WAN IP from [Applications] > [Wake on LAN/WAN] – Wake on WAN tab
7. Support for network monitoring protocol IPFIX (Netflow)
8. Firewall can restrict/drop unwanted inbound WAN traffic such as VPN requests
9. SNMP 'ifLastChange' is now supported for WAN and LAN port uptime (Physical port link up/down detection)
10. Webhook feature can now be enabled in [System Maintenance] > [Webhook] to send periodic keepalive / heartbeat messages to a monitoring server
11. Cache password for auto reconnect option added on the [VPN and Remote Access] > [OpenVPN] > [Client Config] page
12. New VDSL modem code 8D1C17 added in MDM4 firmware

Improvements

1. DNS Filter now supports blocking of DoH (DNS over HTTPS) and DoT (DNS over TLS) services to ensure that users use standard DNS, allowing the DNS Filter to operate optimally
2. Hardware Acceleration is now enabled by default for new routers & factory default settings
3. Exception list added to [Hardware Acceleration]
4. Updated MyVigor authentication method used for Web Content Filter license validation
5. Improved performance for Hotspot Web Portal
6. Wake on LAN via WAN did not work after rebooting the router

7. Syslog now reports more details for unsuccessful OpenVPN connections
8. Hostnames are also supported in the remote management ACL
9. Function priority and default value change for DoS & Bandwidth Limit and HW NAT settings
10. When Brute Force Protection is disabled, service options are greyed-out (ticked by default)
11. In some circumstances Conditional DNS Forwarding did not work
12. Improved mesh network connectivity
13. Fixed a display issue with Basic Configuration Sync in the Mesh setup section
14. Self-sign certificate renewal mechanism improvements related to DrayDDNS Let's Encrypt
15. Disabling a static route could disable the default route entry
16. MDM3 firmware was affected by an issue where switching to ADSL modem code for synchronising did not work
17. After the firmware upgrade, router could stop responding if VoIP call, and VLAN configuration were in use
18. Self-signed certificate will now automatically regenerate before expiring
19. Customized List data information display issue fixed for [LAN] > [General Setup], DHCP Server Option section

Known Issues

(None)

| | |
|-------------------|--|
| Firmware Version | 4.3.2.1_BT (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 26 th October 2021 |
| Release Date | 10 th November 2021 |
| Revision | 10746_1812_a560c17e45 |
| Applicable Models | Vigor2765, Vigor2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

New Features

(None)

Improvements

1. Self-signed certificate will automatically regenerate before expiration
2. System stability improvements
3. Hardware Acceleration did not work with WAN to LAN sessions in routing mode
4. MDM3 firmware could not switch to ADSL modem code

Known Issues

(None)

| | |
|-------------------|--|
| Firmware Version | 4.3.1.2_BT (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 28 th June 2021 |
| Release Date | 30 th July 2021 |
| Revision | 8511_1798_42887b3b41 |
| Applicable Models | Vigor2765, Vigor2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

New Features

(None)

Improvements

1. Wireless security configuration improvements related to encrypted WDS mode

Known Issues

(None)

| | |
|-------------------|--|
| Firmware Version | 4.3.1.1_BT (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 27 th May 2021 |
| Release Date | 11 th June 2021 |
| Revision | 8000_1797_5da3b79358 |
| Applicable Models | Vigor2765, Vigor2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

New Features

(None)

Improvements

1. Update WiFi security for CVE-2020-26139 to CVE-2020-26145, and for CVE-2020-24586 to CVE-2020-24588

Known Issues

(None)

| | |
|-------------------|--|
| Firmware Version | 4.3.1_BT (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 26 th April 2021 |
| Release Date | 20 th May 2021 |
| Revision | 6988_1790_7d830fb99 |
| Applicable Models | Vigor2765, Vigor2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

New Features

1. Mesh is now available on Vigor 2765 routers with wireless (ac,Vac)
2. Added support for multi-language WUI
3. Hardware acceleration with QoS
4. WPA3/OWE for wireless LAN 2.4G/5G clients
5. TOTP 2-factor authentication (Google Authenticator) is now available for authenticating web interface administrator access from the Internet

Improvements

1. VPN Graph is now available in the [Diagnostics] section
2. Full wildcards can be used with DNS Forwarding settings
3. The LAN DNS / DNS Forwarding configuration profiles improvements
4. Colour labels added for different port speeds on the [Dashboard]
5. API String updated for "VibeActiveMedia.com" on SMS profile list
6. Added support for two ISP accounts (PPPoE/PPPoA) with the same WAN interface
7. A warning message will appear for reused IP object / IP Group profile that has already been used by other applications
8. A hostname can be used on 'Access List from the Internet' on [System Maintenance] > [Management] page
9. LAN DNS did not work properly with previous 4.2.3 firmware
10. Restoring a VPN backup file did not work
11. Improved the keyword group configuration via telnet
12. The DHCP IP pool count allowed only 3 addresses for "/29" IP Routed Subnet
13. Interfaces selected in a Filter Rule Direction (Advanced) remained unselected after saving
14. Incorrect time zone used for Mail Alert and Notification Mail when Daylight Saving was enabled
15. Schedules can now be applied to profiles for VPN Remote Dial-In

| | |
|-------------------|---------------------------------------|
| Firmware Version | 4.2.3_BT (Formal Release) |
| Release Type | Initial Release |
| Build Date | 19 th February 2021 |
| Release Date | 23 rd March 2021 |
| Revision | 4586_777_90c1a38 |
| Applicable Models | Vigor2765, Vigor2765ac, Vigor 2765Vac |
| VDSL Modem Code | 8D1B17 |
| ADSL Modem Code | 8D0E11 |
| Locale | UK & Ireland Only |

First Firmware Release for this model

New Features

(None)

Improvements

(None)

[END OF FILE]