

Release Notes for VigorConnect (UK/Ireland)

| | |
|-----------------------------|--|
| Software Version | 1.7.0 (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Release Date | 30 th January 2023 |
| Supported Operating Systems | 64-bit Windows 7 and later versions of Windows, Raspberry Pi, 64-bit Linux distros including Ubuntu, OpenSUSE, CentOS, Debian, and RedHat, Synology NAS (x86 system) |
| Locale | UK & Ireland Only |

| VigorConnect Firmware Requirements | | | |
|---|-------------------------|--------------------------|-------------------------|
| VigorAP Model | Minimum Firmware | VigorSwitch Model | Minimum Firmware |
| VigorAP 710 | 1.2.3 or later | VigorSwitch G1080 | 1.05.0 or later |
| VigorAP 802 | 1.3.2 or later | VigorSwitch G1085 | 2.5.1 or later |
| VigorAP 810 | 1.2.3 or later | VigorSwitch G1280 | 2.5.1 or later |
| VigorAP 902 | 1.2.3 or later | VigorSwitch G2100 | 2.6.5 or later |
| VigorAP 903 | 1.3.2 or later | VigorSwitch G2280 | 2.5.1 or later |
| VigorAP 910C | 1.2.3 or later | VigorSwitch G2280x | 2.5.1 or later |
| VigorAP 912C | 1.3.3 or later | VigorSwitch G2500 | 2.5.1 or later |
| VigorAP 918R | 1.3.0 or later | VigorSwitch G2540x | 2.6.4 or later |
| VigorAP 920R | 1.3.0 or later | VigorSwitch P1085 | 2.5.1 or later |
| VigorAP 960C | 1.4.0 or later | VigorSwitch P1092 | 1.05.0 or later |
| VigorAP 1000C | 1.3.2 or later | VigorSwitch P1280 | 2.5.1 or later |
| VigorAP 1060C | 1.4.1 or later | VigorSwitch P2100 | 2.6.5 or later |
| | | VigorSwitch P2121 | 2.5.1 or later |
| | | VigorSwitch P2280 | 2.5.1 or later |
| | | VigorSwitch P2280x | 2.5.1 or later |
| | | VigorSwitch P2500 | 2.5.1 or later |
| | | VigorSwitch P2540x | 2.6.4 or later |

New Features

(None)

Improvements

1. The VPN parser functionality added into the Syslog module
2. The Service Control and Reboot System functions added
3. The Universal Repeater configuration page can be used for the Range Extender mode
4. Support for VPN functionality added
[Monitoring] > [VPN]
[Configuration] > [VPN Analytics Setup]

Known Issues

1. While viewing sFlow FireFox (HTTPS) may block invalid HTTPS certificate issued by Grafana

| | |
|-----------------------------|--|
| Software Version | 1.6.2 (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Release Date | 10 th February 2022 |
| Supported Operating Systems | 64-bit Windows 7 and later versions of Windows, Raspberry Pi, 64-bit Linux distros including Ubuntu, OpenSUSE, CentOS, Debian, and RedHat, Synology NAS (x86 system) |
| Locale | UK & Ireland Only |

| VigorConnect Firmware Requirements | | | |
|---|-------------------------|--------------------------|-------------------------|
| VigorAP Model | Minimum Firmware | VigorSwitch Model | Minimum Firmware |
| VigorAP 710 | 1.2.3 or later | VigorSwitch G1080 | 1.05.0 or later |
| VigorAP 802 | 1.3.2 or later | VigorSwitch G1085 | 2.5.1 or later |
| VigorAP 810 | 1.2.3 or later | VigorSwitch G1280 | 2.5.1 or later |
| VigorAP 902 | 1.2.3 or later | VigorSwitch G2100 | 2.6.5 or later |
| VigorAP 903 | 1.3.2 or later | VigorSwitch G2280 | 2.5.1 or later |
| VigorAP 910C | 1.2.3 or later | VigorSwitch G2280x | 2.5.1 or later |
| VigorAP 912C | 1.3.3 or later | VigorSwitch G2500 | 2.5.1 or later |
| VigorAP 918R | 1.3.0 or later | VigorSwitch G2540x | 2.6.4 or later |
| VigorAP 920R | 1.3.0 or later | VigorSwitch P1085 | 2.5.1 or later |
| VigorAP 960C | 1.4.0 or later | VigorSwitch P1092 | 1.05.0 or later |
| VigorAP 1000C | 1.3.2 or later | VigorSwitch P1280 | 2.5.1 or later |
| VigorAP 1060C | 1.4.1 or later | VigorSwitch P2100 | 2.6.5 or later |
| | | VigorSwitch P2121 | 2.5.1 or later |
| | | VigorSwitch P2280 | 2.5.1 or later |
| | | VigorSwitch P2280x | 2.5.1 or later |
| | | VigorSwitch P2500 | 2.5.1 or later |
| | | VigorSwitch P2540x | 2.6.4 or later |

New Features

1. VigorConnect can be run on Synology NAS (x86 system)

Improvements

1. Fixed the AP profile 5GHz channel bandwidth selection

Known Issues

1. While viewing sFlow FireFox (HTTPS) may block invalid HTTPS certificate issued by Grafana

| | |
|-----------------------------|---|
| Software Version | 1.5.2 (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Release Date | 20 th May 2021 |
| Supported Operating Systems | 64-bit Windows 7 and later versions of Windows 64-bit Linux distros including Ubuntu, OpenSUSE, CentOS, Debian, and RedHat |
| Locale | UK & Ireland Only |

| VigorConnect Firmware Requirements | | | |
|---|-------------------------|-----------------------------|-------------------------|
| VigorAP Model | Minimum Firmware | VigorSwitch Model | Minimum Firmware |
| VigorAP 710 | 1.2.3 or later | VigorSwitch G1280 & P1280 | 2.5.1 or later |
| VigorAP 802 | 1.3.2 or later | VigorSwitch G2280 & P2280 | 2.5.1 or later |
| VigorAP 810 | 1.2.3 or later | VigorSwitch G2280x & P2280x | 2.5.1 or later |
| VigorAP 902 | 1.2.3 or later | VigorSwitch G2500 & P2500 | 2.5.1 or later |
| VigorAP 903 | 1.3.2 or later | VigorSwitch G2540x & P2540x | 2.6.4 or later |
| VigorAP 910C | 1.2.3 or later | VigorSwitch P2121 | 2.5.1 or later |
| VigorAP 912C | 1.3.3 or later | VigorSwitch G1080 | 1.05.0 or later |
| VigorAP 918R | 1.3.0 or later | VigorSwitch G1085 & P1085 | 2.5.1 or later |
| VigorAP 920R | 1.3.0 or later | VigorSwitch P1092 | 1.05.0 or later |
| VigorAP 960C | 1.4.0 or later | | |
| VigorAP 1000C | 1.3.2 or later | | |
| VigorAP 1060C | 1.4.1 or later | | |

New Features

1. VigorConnect can be run on Linux distros including Ubuntu, OpenSUSE, CentOS, Debian, and RedHat
2. Support for VigorAP 1060C
3. Support for syslog

Improvements

(None)

Known Issues

1. While viewing sFlow FireFox (HTTPS) may block invalid HTTPS certificate issued by Grafana

| | |
|-----------------------------|--|
| Software Version | 1.5.1 (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Release Date | 23 rd September 2020 |
| Supported Operating Systems | 64-bit Windows 7 and later versions of Windows |
| Locale | UK & Ireland Only |

| VigorConnect Firmware Requirements | | | |
|---|-------------------------|-----------------------------|-------------------------|
| VigorAP Model | Minimum Firmware | VigorSwitch Model | Minimum Firmware |
| VigorAP 710 | 1.2.3 or later | VigorSwitch G1280 & P1280 | 2.5.1 or later |
| VigorAP 802 | 1.3.2 or later | VigorSwitch G2280 & P2280 | 2.5.1 or later |
| VigorAP 810 | 1.2.3 or later | VigorSwitch G2280x & P2280x | 2.5.1 or later |
| VigorAP 902 | 1.2.3 or later | VigorSwitch G2500 & P2500 | 2.5.1 or later |
| VigorAP 903 | 1.3.2 or later | VigorSwitch G2540x & P2540x | 2.6.4 or later |
| VigorAP 910C | 1.2.3 or later | VigorSwitch P2121 | 2.5.1 or later |
| VigorAP 912C | 1.3.3 or later | VigorSwitch G1080 | 1.05.0 or later |
| VigorAP 918R | 1.3.0 or later | VigorSwitch G1085 & P1085 | 2.5.1 or later |
| VigorAP 920R | 1.3.0 or later | VigorSwitch P1092 | 1.05.0 or later |
| VigorAP 1000C | 1.3.2 or later | | |

New Features

(None)

Improvements

1. Improved the AP Mesh Root selection mechanism

Known Issues

1. While viewing sFlow FireFox (HTTPS) may block invalid HTTPS certificate issued by Grafana

| | |
|-----------------------------|--|
| Software Version | 1.5.0 (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Release Date | 3 rd July 2020 |
| Supported Operating Systems | 64-bit Windows 7 and later versions of Windows |
| Locale | UK & Ireland Only |

| VigorConnect Firmware Requirements | | | |
|---|-------------------------|-----------------------------|-------------------------|
| VigorAP Model | Minimum Firmware | VigorSwitch Model | Minimum Firmware |
| VigorAP 710 | 1.2.3 or later | VigorSwitch G1280 & P1280 | 2.5.1 or later |
| VigorAP 802 | 1.3.2 or later | VigorSwitch G2280 & P2280 | 2.5.1 or later |
| VigorAP 810 | 1.2.3 or later | VigorSwitch G2280x & P2280x | 2.5.1 or later |
| VigorAP 902 | 1.2.3 or later | VigorSwitch G2500 & P2500 | 2.5.1 or later |
| VigorAP 903 | 1.3.2 or later | VigorSwitch P2121 | 2.5.1 or later |
| VigorAP 910C | 1.2.3 or later | VigorSwitch G1080 | 1.05.0 or later |
| VigorAP 912C | 1.3.3 or later | VigorSwitch G1085 & P1085 | 2.5.1 or later |
| VigorAP 918R | 1.3.0 or later | VigorSwitch P1092 | 1.05.0 or later |
| VigorAP 920R | 1.3.0 or later | | |
| VigorAP 1000C | 1.3.2 or later | | |

New Features

1. Support for sFlow monitoring for use with switches that support the feature, such as the VigorSwitch G2280x

Improvements

(None)

Known Issues

(None)

| | |
|-----------------------------|--|
| Software Version | 1.4.0 (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Release Date | 8 th April 2020 |
| Supported Operating Systems | 64-bit Windows 7 and later versions of Windows |
| Locale | UK & Ireland Only |

| VigorConnect Firmware Requirements | | | |
|---|-------------------------|-----------------------------|-------------------------|
| VigorAP Model | Minimum Firmware | VigorSwitch Model | Minimum Firmware |
| VigorAP 710 | 1.2.3 or later | VigorSwitch G1280 & P1280 | 2.5.1 or later |
| VigorAP 802 | 1.3.2 or later | VigorSwitch G2280 & P2280 | 2.5.1 or later |
| VigorAP 810 | 1.2.3 or later | VigorSwitch G2280x & P2280x | 2.5.1 or later |
| VigorAP 902 | 1.2.3 or later | VigorSwitch G2500 & P2500 | 2.5.1 or later |
| VigorAP 903 | 1.3.2 or later | VigorSwitch P2121 | 2.5.1 or later |
| VigorAP 910C | 1.2.3 or later | VigorSwitch G1080 | 1.05.0 or later |
| VigorAP 912C | 1.3.3 or later | VigorSwitch P1092 | 1.05.0 or later |
| VigorAP 918R | 1.3.0 or later | | |
| VigorAP 920R | 1.3.0 or later | | |
| VigorAP 1000C | 1.3.2 or later | | |

New Features

1. Support for Mesh network management in [NETWORK MENU] > [Configuration] > [Mesh]

Improvements

1. The time setting parameter (CheckLatestSoftwareVersionTime) is adjustable and is effective when "Auto check and download..." is selected as Upgrade Method on [SYSTEM MENU] > [About] > [Update]
2. Last 10 SNMP events and TX/RX monitor items added on the Dashboard
3. Software installation improvements:
 - a. SNMP configuration setup added
 - b. Allow VigorConnect to pass through Windows Firewall

Known Issues

(None)

| | |
|-----------------------------|--|
| Software Version | 1.3.1 (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Release Date | 13 th February 2020 |
| Supported Operating Systems | 64-bit Windows 7 and later versions of Windows |
| Locale | UK & Ireland Only |

| VigorConnect Firmware Requirements | | | |
|---|-------------------------|-----------------------------|-------------------------|
| VigorAP Model | Minimum Firmware | VigorSwitch Model | Minimum Firmware |
| VigorAP 710 | 1.2.3 or later | VigorSwitch G1280 & P1280 | 2.5.1 or later |
| VigorAP 802 | 1.3.2 or later | VigorSwitch G2280 & P2280 | 2.5.1 or later |
| VigorAP 810 | 1.2.3 or later | VigorSwitch G2280x & P2280x | 2.5.1 or later |
| VigorAP 902 | 1.2.3 or later | VigorSwitch G2500 & P2500 | 2.5.1 or later |
| VigorAP 903 | 1.3.2 or later | VigorSwitch P2121 | 2.5.1 or later |
| VigorAP 910C | 1.2.3 or later | VigorSwitch G1080 | 1.05.0 or later |
| VigorAP 912C | 1.3.3 or later | VigorSwitch P1092 | 1.05.0 or later |
| VigorAP 918R | 1.3.0 or later | | |
| VigorAP 920R | 1.3.0 or later | | |

New Features

1. VigorConnect can now manage VigorAP 912C, and VigorAP 918R/RPD

Improvements

(None)

Known Issues

(None)

| | |
|-----------------------------|--|
| Software Version | 1.3.0 (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Release Date | 15 th January 2020 |
| Supported Operating Systems | 64-bit Windows 7 and later versions of Windows |
| Locale | UK & Ireland Only |

| VigorConnect Firmware Requirements | | | |
|---|-------------------------|-----------------------------|-------------------------|
| VigorAP Model | Minimum Firmware | VigorSwitch Model | Minimum Firmware |
| VigorAP 710 | 1.2.3 or later | VigorSwitch G1280 & P1280 | 2.5.1 or later |
| VigorAP 802 | 1.3.2 or later | VigorSwitch G2280 & P2280 | 2.5.1 or later |
| VigorAP 810 | 1.2.3 or later | VigorSwitch G2280x & P2280x | 2.5.1 or later |
| VigorAP 902 | 1.2.3 or later | VigorSwitch G2500 & P2500 | 2.5.1 or later |
| VigorAP 903 | 1.3.2 or later | VigorSwitch P2121 | 2.5.1 or later |
| VigorAP 910C | 1.2.3 or later | VigorSwitch G1080 | 1.05.0 or later |
| VigorAP 920R | 1.3.0 or later | VigorSwitch P1092 | 1.05.0 or later |

New Features

1. VigorConnect can now manage VigorSwitch G1080 and P1092

Improvements

1. Add a function of searching devices on the **Dashboard**; **[New Devices]** section.
2. The search results of **[Configuration] > [Wireless Wizard]** won't include VigorSwitch(es)
3. Add the options of System Log and Login Log on **[SYSTEM MENU] > [System] > [Logs]**
4. Add the check box for each option to enable / disable the configuration setting for AP profile

Known Issues

(None)

| | |
|-----------------------------|--|
| Software Version | 1.2.0 (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Release Date | 10 th January 2020 |
| Supported Operating Systems | 64-bit Windows 7 and later versions of Windows |
| Locale | UK & Ireland Only |

| VigorConnect Firmware Requirements | | | |
|---|-------------------------|-----------------------------|-------------------------|
| VigorAP Model | Minimum Firmware | VigorSwitch Model | Minimum Firmware |
| VigorAP 710 | 1.2.3 or later | VigorSwitch G1280 & P1280 | 2.5.1 or later |
| VigorAP 802 | 1.3.2 or later | VigorSwitch G2280 & P2280 | 2.5.1 or later |
| VigorAP 810 | 1.2.3 or later | VigorSwitch G2280x & P2280x | 2.5.1 or later |
| VigorAP 902 | 1.2.3 or later | VigorSwitch G2500 & P2500 | 2.5.1 or later |
| VigorAP 903 | 1.3.2 or later | VigorSwitch P2121 | 2.5.1 or later |
| VigorAP 910C | 1.2.3 or later | | |
| VigorAP 920R | 1.3.0 or later | | |

New Features

1. VigorConnect can now manage and provision DrayTek VigorSwitch switches on the local network

Improvements

1. Device name auto detect function added
2. Change of the file naming rule of the backup configuration
3. The “Add” button will appear only when new devices are detected and displayed on New Devices list
4. Wireless Wizard improvements:
 - a. VLAN tag configuration for guests and main SSID added
 - b. Station Control added
5. AP Profile improvements:
 - a. Quick Mode added to **[NETWORK MENU] > [Configuration] > [AP Profile] > [Profile Settings]**
 - b. TR-069 STUN server settings added
 - c. Mesh Mode added
 - d. Wireless 5G-2 can be configured

Known Issues

(None)

| | |
|-----------------------------|--|
| Software Version | 1.1.2 (First Software Release) |
| Release Type | Initial Release |
| Release Date | 27 th August 2019 |
| Supported Operating Systems | 64-bit Windows 7 and later versions of Windows |
| Locale | UK & Ireland Only |

| VigorConnect Firmware Requirements | |
|---|-------------------------|
| Model | Minimum Firmware |
| VigorAP 710 | 1.2.3 or later |
| VigorAP 810 | 1.2.3 or later |
| VigorAP 900 | 1.2.3 or later |
| VigorAP 902 | 1.2.3 or later |
| VigorAP 903 | 1.3.2 or later |
| VigorAP 910C | 1.2.3 or later |
| VigorAP 920R | 1.3.0 or later |

VigorConnect is an easy to install Central Management system for DrayTek products, for rapid deployment and group management of VigorAP access points.

Provision VigorAPs, monitor the status and usage of groups of VigorAPs on your network. Schedule firmware upgrades out-of-hours and perform routine configuration backups.

For more information see:

<https://www.draytek.co.uk/information/vigorconnect/>

New Features

(None)

Improvements

(None)

Known Issues

(None)

[END OF FILE]