

Release Notes for DrayTek VigorSwitch PQ1070x (UK/Ireland)

| | |
|-------------------|--|
| Firmware Version | 1.58.2 (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 22 nd April 2026 |
| Release Date | 13 th May 2026 |
| Build Revision | ae40fc9 |
| Applicable Models | VigorSwitch PQ1070x |
| Locale | UK & Ireland Only |

New Features

1. Support for LED self-test on boot

Improvements

1. Enhanced LLDP web user interface
2. Increased LLDP Time to Live up to 120 seconds
3. Reduced time for firmware updates via HTTPS
4. LLDP ports are enabled by default in [Advanced] > [LLDP] Settings and Status
5. Default username (“admin”) is displayed during the initial password change at first login
6. Added support for sending LLDP System Description and System Capabilities information
7. Resolved issue where changing the login password failed after using the browser’s translation feature
8. Fix connection issue to VigorSwitch via IPv6 HTTPS
9. Addressed problem with the DHCPv6 client being unable to obtain IPv6 address
10. Improved display of SFP port link status on the dashboard when zooming in or out of the webpage

Known Issues

1. When using the SFP module (DrayTek SFP, FPCOPT-RJ-D) for network connections, transmission speed must be set to 1000Mbps

Notes

1. After upgrading the firmware to version 1.58.2, the device will require 20 to 70 seconds to restart on its first reboot

| | |
|-------------------|--|
| Firmware Version | 1.58.1 (Formal Release) |
| Release Type | Regular – Upgrade recommended when convenient |
| Build Date | 17 th December 2025 |
| Release Date | 19 th February 2026 |
| Build Revision | 9934a97 |
| Applicable Models | VigorSwitch PQ1070x |
| Locale | UK & Ireland Only |

New Features

1. Support for 802.1Q VLAN
2. Support for MyVigor to obtain related services
3. Router-based Central Switch Management compatibility added for certain Vigor routers

Improvements

1. A CPU overload was caused by multicast streaming packets
2. The NTP packets could not be send without a DNS server IP address
3. Compatibility improvements with the SFP module DrayTek ES-T2-RJ45 (10/100/1000M)
4. Fix an issue with a configuration error related to the 10G SFP port number in [Advanced] > [Port Mirror]
5. Changing the STP status (enable/disable) could cause issues with the change of edge port, and some system stability

| | |
|-------------------|-------------------------------|
| Firmware Version | 1.58.0 (Formal Release) |
| Release Type | First Firmware Release |
| Build Date | 22 nd August 2025 |
| Release Date | 9 th December 2025 |
| Build Revision | 15561ad |
| Applicable Models | VigorSwitch PQ1070x |
| Locale | UK & Ireland Only |

First Firmware Release

[END OF FILE]