# Release Notes for DrayTek VigorSwitch P2282x (UK/Ireland)

| | |
|---|---|
| Firmware Version | 2.10.2 (Formal Release) |
| Release Type | **Regular** – Upgrade recommended when convenient |
| Build Date | 22nd August 2025 |
| Release Date | 3rd October 2025 |
| Build Revision | 41baf69 |
| Applicable Models | VigorSwitch P2282x |
| Locale | UK & Ireland Only |

**New Features**

(none)

**Improvements**

1. Improvements to the stacking feature
2. Stacking mode can also support LAG ports in Static MAC, VLAN, GVRP, Multicast, STP, QoS, ONVIF Surveillance, IP Source Guard, Port Security, Dynamic ARP Inspection, DHCP Snooping, IP Conflict Prevention, Loop Protection, and Port Recovery

**Known Issues**

(none)

| Firmware Version | 2.10.1 (Formal Release) |
|---|---|
| Release Type | **Regular** – Upgrade recommended when convenient |
| Build Date | 10th April 2025 |
| Release Date | 22nd May 2025 |
| Build Revision | b312861 |
| Applicable Models | VigorSwitch P2282x |
| Locale | UK & Ireland Only |

## New Features

1. Support for up to four devices for Physical Stacking

## Improvements

1. Optimising the Physical Stacking mechanism

## Known Issues

(none)

| Firmware Version | 2.9.7 (Formal Release) |
|---|---|
| Release Type | **Regular** – Upgrade recommended when convenient |
| Build Date | 14<sup>th</sup> March 2025 |
| Release Date | 9<sup>th</sup> May 2025 |
| Build Revision | 59996db |
| Applicable Models | VigorSwitch P2282x |
| Locale | UK & Ireland Only |

**New Features**

(none)

**Improvements**

1. Improvements to the Web GUI security
2. Improvements to the DNS domain registration with TR-069 service

**Known Issues**

(none)

| Firmware Version | 2.9.5 (Formal Release) |
|---|---|
| Release Type | **Regular** – Upgrade recommended when convenient |
| Build Date | 15<sup>th</sup> July 2024 |
| Release Date | 18<sup>th</sup> November 2024 |
| Build Revision | ef29dcb |
| Applicable Models | VigorSwitch P2282x |
| Locale | UK & Ireland Only |

**New Features**

(none)

**Improvements**

1. Improvements to the TR-069 parameter related issues
2. The CPU usage mechanism improvements
3. Fix an issue related to the IP Source Guard and DHCP snooping used simultaneously

**Known Issues**

(none)

| Firmware Version | 2.9.4 (Formal Release) |
|---|---|
| Release Type | **Regular** – Upgrade recommended when convenient |
| Build Date | 19th April 2024 |
| Release Date | 06th August 2024 |
| Build Revision | 24df0f6 |
| Applicable Models | VigorSwitch P2282x |
| Locale | UK & Ireland Only |

**New Features**

(none)

**Improvements**

1. Password mechanism changed to force admin to change the password from the default password
2. The ICP table size increased to 1024
3. Port Description added on the Bandwidth Utilization page
4. The configuration process for LAG has been updated
5. The firmware release notifications mechanism added
6. The syslog display time adjustments related to the daylight-saving time
7. The SFP+ port information can be displayed on the dashboard
8. The management port configuration option improvements
9. The device MAC address details included in syslog

**Known Issues**

(none)

| Firmware Version | 2.9.3 (Formal Release) |
|---|---|
| Release Type | **Initial Release** |
| Build Date | 11th March 2024 |
| Release Date | 09th May 2024 |
| Build Revision | 35dae59 |
| Applicable Models | VigorSwitch P2282x |
| Locale | UK & Ireland Only |

**First Firmware Release**


**[END OF FILE]**